

Di O Date. <u>00/10/2</u>	2014	_ Loan #:		
Broker Informat	ion:			
Company: <u>F.C.TUC</u>	CKER 5 STAR REAL E	STATEBRAD TAFLINGER		
	3417 W. BETHEL A			
City: MUNCIE		State: <u>IN</u>	ZIP Code:	47304
Phone: <u>765-289-24</u> THEMOVINGMACHII		Fax: <u>765-289-2425</u>	Email:	
Subject Property	<u>v:</u>			
Name of Borrower(s	:):_tax ease florida r	EO LLC		
Street Address: <u>16</u>	17 W. 11 [™] ST.			
City: MUNCIE		State: <u>IN</u>	ZIP Code: 473	02_
Date Initial Property	Inspection:	08/14/2014		
Is MLS Available in yo	our Area? Yes 🛛 No	☐ Will Property be listed i	in MLS? Yes 🛛 No	
Neighborhood D	ata:			
Location:	Urban 🖂	Suburban	Rural	
Growth Rate:	Rapid 🗌	Stable	Slow	
Property Values:	Increasing \square	Stable 🖂	Declining	
Demand/Supply:	Shortage	Normal \boxtimes	Oversupply	
Market Time:	Under 3m	3-6 mos \square	Over 6mos	
Price Range	High \$:	10000 Low\$: <u>65900</u>	0	
Marketability:				
Describe any neigh OK AREA, CITY PA		market conditions that will a	affect the marketin	g of this property.

Is the Property Secure?	Yes 🖂	No [
--------------------------------	-------	------	--

Marketing Strategy: LIST AT @ \$12,000.00. I AM A MEMBER OF 2 MLS BOARDS AND COVERS MOST OF THE STATE OF INDIANA.

Condition a	and Repair	<u>Estimates:</u>											
General Condit	ion: 🗌 Good	☐ Average	⊠ Fair	Poor	☐ Vandalized	☐ Fire Damage							
		<u>List Suggest</u>	Agent Estimates										
Exterior Paint:	PAINT EXTER	IOR SIDING, TR	SIDING, TRIM AND WINDOWS \$3500										
Interior Paint:	PAINT INTERI	OR	\$2000										
Carpet:	NEW FLOOR (COVERING					\$2000						
Other Flooring:	DRYWALL RE	PAIRS					\$1000						
Kitchen:							\$						
Bathroom(s):	REPLACE MIS	SING TOILET					\$300						
Plumbing:							\$						
Electrical:	REPLACE SOF	FIT & FASCIA	-EXTERIOR				\$200						
Roofing:	NEEDS ROOF	DF REPAIRS \$1000											
Cleaning:	REPLACE 3 BR	ROKEN WINDOV	VS				\$300						
Landscaping:	NEEDS LANDS	SCAPING	PING \$500										
Other:	TRASHOUT		\$1500										
						Total Estimate	\$12,300.00						
-	nd Inspec tooker's Initial		f Accessil	ole Areas,	Additional Rep	orts Are Recomme	nded:						
☐ Winterize		Гermite	⊠ Roof		☐ Well	☐ Septic	☐ Electrical						
□ Plumbing	□ H	☐ Other											
Pricing:													
			Pricing			able Buyer	\neg						
-	As-Is Price:	\$12000			INVESTOR								
•	Repair Price												
	ded List Price	·											
30day "Quic	k" sale as-is	\$10000											
Monthly rent	t amount:	\$450.00)										

DO YOU RECOMMEND SELLING AS/IS OR REPAIRED? AS-IS

Please detail subject property's characteristics with respect to the following:

Location:
1617 W. 11 TH ST. MUNCIE, IN 47302
Condition of the Roof: Repair Replace OK
EVIDENCE OF LEAKS IN LIVING ROOM, DEPENDS IF YOU WANT TO REPAIR OR LIST AS-IS
Condition of the Interior: Water Damage? Yes No
EVEIDENCE OF ROOF LEAKING IN LIVING ROOM. THE FURNACE HAS NOT BEEN UPDATED, THE FURNACE IS A COAL FURNACE THAT HAS BEEN COVERTED INTO GAS FORCED AIR.
Condition of the Exterior:
FAIR, PEELING PAINT.
Market Conditions:
STABLE, THERE ARE 47 ACTIVE LISTINGS WITHIN 1 MILE OF SUBJECT, THERE ARE 17 SOLD IN LAST 6 MONTHS. A LOT OF ACTIVITY. ALL SOLD AND ACTIVE COMPS ARE REO PROPERTIES.
Unemployment Rate:
AVERAGE
Comments:
SUBJECT HAS SHINGLE SIDING, ENCLOSD FRONT PORCH, CORNER LOT AND HAS A CHAIN LINK FENCED BACK YARD, LARGE CONCRETE SLAB IN BACK YARD FOR BASKETBALL COURT.
Positive features:
NONE

Comp Sheet:

Subject Address	Sq. Ft.	Bed	Bath	Age	Condition	Garage # of Car	Pool	Lot Size	Extras
1617 W. 11 [™] ST MUNCIE, IN 47302	1092	2	1	114	FAIR	NA	NA	.14AC	ENCLOSED PORCH, ENCLOSED PORCH

Comparable Listings:

Comparable Listing Address	Sq. Ft.	Bed	Bath	Age	Condition	Garage # of Car	Pool	List Date	Orig. List Price	Current List Price	Distance to subject
1504 W. 13 [™] ST. MUNCIE, IN 47302	792	2	1	40	FAIR	1.5 CD	NA	6/10/14	10000	10000	2 BLKS
615 W. 14 TH ST. MUNCIE, IN 47302	1130	3	1	84	FAIR	NA	NA	6/19/14	16900	16900	3 BLKS
1300 W. 16 [™] ST. MUNCIE, IN 47302	896	2	1	84	FAIR	NA	NA	7/31/14	17500	17500	5 BLKS

Comparable Sales:

Comparable Sales Address	Sq. Ft.	Bed	Bath	Age	Condition	Garage # of Car	Pool	List Date	Orig. List Price	Sold Price	Distance to subject
1207 W. 15 TH ST. MUNCIE, IN 47302	768	2	1	78	FAIR	1.5 CD	NA	2/9/14	8800	7500	4 BLKS
1317 W. MEMORIAL MUNCIE, IN 47302	720	2	1	96	FAIR	2 CD	NA	1/22/14	14900	11500	7 BLKS
709 W. 11 [™] ST. MUNCIE, IN 47302	780	2	1	95	FAIR	NA	NA	3/28/14	13500	12000	1 BLK

Comparable listing Comments:

ALL COMPS ARE WITHIN .50 MILES OF SUBJECT. ALL COMPS ARE THE SAME STYLE, CONDITION, AGE, ROOM COUNT AND SIMILAR GLA. ACTIVE COMP 1 IS SUPERIOR TO SUBJECT DUE TO ITS AGE. ACTIVE COMP 2 IS THE MOST EQUAL TO SUBJECT'S AMENITIES. ACTIVE COMP 3 IS INFERIOR TO SUBJECT DUE TO ITS GLA.

Comparable Sales Comments:

ALL COMPS ARE WITHIN .50 MILES OF SUBJECT. ALL COMPS ARE THE SAME STYLE, CONDITION, AGE, ROOM COUNT AND SIMILAR GLA. SOLD COMP 1 IS SUPERIOR TO SUBJECT DUE TO ITS AGE. SOLD COMP 2 IS INFERIOR TO SUBJECT DUE TO ITS GLA. SOLD COMP 3 IS THE MOST EQUAL TO SUBJECT'S AMENITIES.



Checklist of Damages

Is there any vandalism?: Yes $oxed{oxed}$ No $oxed{oxed}$ If yes, Where?
3 BROKEN WINDOWS
Is there any graffiti?: Yes $oxtimes$ No $oxtimes$ If yes, Where?
Is there any damage that appears to be caused by an act of nature?: Yes \square No \boxtimes If yes, Where?
Are there any broken windows?: Yes 🛛 No 🗌 If yes, Where?
3 BROKEN WINDOWS, I HAVE BOARDED THEM UP.
Are there any walls with holes larger than a quarter?: Yes □ No ☑ If yes, Where?
Are there any broken doors?: Yes ☐ No ☒ If yes, Where?
Are there any tears or holes in carpet or vinyl, or missing flooring? : Yes \(\sum \) No \(\sum \) If yes, Where?
Are there any signs of water damage or mold present?: Yes ⊠No ☐ If yes, Where?
WATER DAMAGE TO CEILING IN LIVING ROOM, NO MOLD
Does anything appear to be missing? (i.e., built in appliances, cabinets, interior doors, water heater) : Yes \(\sum \) No \(\sum \) If yes, Where?
Are there any signs of water damage or mold present?: Yes No If yes, Where?
WATER DAMAGE TO CEILING IN LIVING ROOM. NO MOLD