Five Online Inspection Results

FIVE BROTHERS PROPERTY INSPECTION RESULT

Exterior Only
Order: 10686617

| Account #:/FHA Case Number | Inspection Type: | Date Ordered:/Ordered By: | | |
|--|-------------------------------------|---------------------------|--|--|
| invantl000040 / | VERIFY OCC - DRIVE BY | 9/10/2014 / petersonm | | |
| Account Type: | Department: | Date Completed: | | |
| FHA | COLLECTION | 9/17/2014 | | |
| Address: | First Time Vacant Y/N: | Damage: | | |
| 1645 S GRAND AVE Evansville, IN 47713 | YES First Time Vacant Date: | NO EXTERIOR DAMAGES | | |
| | 9/17/2014 | Property Address: | | |
| | - N/A | GOOD ADDRESS | | |
| | Key Code/Notes: Resecure: | | | |
| Occupied By: | Personal Property: | Utility Water: | | |
| VACANT | NO | OFF | | |
| Occupied Verified By: | Property Guarded: | Utility Gas: | | |
| VISUAL | N/A | OFF | | |
| Occupied Verified By Neighbor #: | Property Secure: | Utility Electric: | | |
| | YES | OFF | | |
| Exterior Condition: | Lawn Height: | For Sale Sign Type: | | |
| GOOD | Under 6 in | NOT FOR SALE | | |
| Neighborhood: | Type of Maintenance Needed: | Realtor Name: | | |
| STABLE Contact Card/Letter Left: | | Property For Rent: | | |
| No card left. Winter Tag Others Left: | Pool Exists: NO | NO Realtor Phone: | | |
| No | Need To Secure Pool: | | | |
| Winter Tag Ours Left: | N/A | Sold Sign: | | |
| No | Need To Remove Debris: | NO | | |
| | N/A | | | |
| External Notes: | | | | |
| Vacant / Secure / No persor | nal property visible /Electric off/ | | | |
| CURRENT KEY CODE IS : | • • • | | | |
| INTERVIEW | | | | |
| No Interview Conducted | | | | |
| ino mierview Conducted | | | | |

| Property Type: | | Property | Property Stories: | | Primary Phone: | | |
|--------------------------------------|------------|----------------------|--|---------------------------|-----------------------|------------------------------|--|
| SINGLE FAMILY Property Construction: | | 1 Property | 1 Property Garage: | | Work Phone: | | |
| FRAME Property Color: WHITE | | | NO GARAGE Property Common Entry: NO | | | | |
| ОИТРИТ: | Invoice #: | Photos#: | Photo Sent: 9/16/2014 5:32:56 AM | Inspection Charge: \$0.00 | Photos Charge: \$0.00 | Total Amount Charged: \$0.00 | |

^{*} This is an exterior inspection of the property: only obvious exterior damages are reported. Damage to the interior of this property is not reported on this inspection.

Account #: invantl000040 Order #: 10686617

Address: 1645 S GRAND AVE Evansville IN 47713




Date Completed: 09/17/2014 10686617-20140915010454361



Case #:

Date Completed: 09/17/2014 10686617-20140915010500678



Date Completed: 09/17/2014 10686617-20140915010505093




Date Completed: 09/17/2014 10686617-20140915010510038

Account #: invantl000040 Order #: 10686617

Address: 1645 S GRAND AVE Evansville IN 47713



Date Completed: 09/17/2014 10686617-20140915011421800





Date Completed: 09/17/2014 10686617-20140915011432657




Case #:

Date Completed: 09/17/2014 10686617-20140915011436417

Account #: invantl000040 Order #: 10686617

Address: 1645 S GRAND AVE Evansville IN 47713 Case #:



Date Completed: 09/17/2014 10686617-20140915011442532



Date Completed: 09/17/2014

fb ftv certificate signature pdf-10686617