

BPO Date: <u>2/28/20</u>)14	Loan #:		
Broker Informat	ion:			
Company: RED HA	T REALTY AND AUCT	<u>ION</u> Agent	: KAROL MCLEOD	
Doing Business As:				
Company Address: _	213 EAST MAI	N		
City: MORGA!	<u>VFIELD</u>	State: <u>KY</u>	ZIP Code: 42437	
Phone: <u>270389037</u>	<u>'0</u>	Fax: <u>2703890470</u>	_ Email:RDHAT101@BELLSOUTH.	NET
Subject Property	/:			
Name of Borrower(s	s):			
City: STURGIS		State: KY	ZIP Code: 42459	
Date Initial Property	Inspection: <u>2/28/2</u>	2014		
		_		
Is MLS Available in yo	ur Area? Yes X No	Will Property be list	ted in MLS? Yes No	
Neighborhood D	ata:			
Location:	Urban	Suburban 🗌	Rural X□	
Growth Rate:	Rapid 🗌	Stable	Slow X	
Property Values:	Increasing	Stable	Declining X	
Demand/Supply:	Shortage	Normal X	Oversupply \square	
Market Time:	Under 3m	3-6 mos	Over 6mos X	
Price Range	High \$:1	40000 Low\$: <u>99</u> 0	00	
Marketability:				
			ll affect the marketing of this pro	•
_			nearest Wal-mart. Sturgis comme	
	on home with junk al		eside a fairly nice house and across	, tile
Will this property b	ecome a problem for	resale? If yes, explain		
. After the interior in	nspection of the subje	ect property I discovered	that it does not have heat or air. (
=			ot finished. The subject property v	
		The property needs to b	water in the toilet bowls. Some of ne trashed out.	the noors
	- Complete pictures):	property fiecds to t		
Is the Property Se	ecure? Yes X 🗌	No 🗌		

Marketing Strategy:

Condition and Repair Es	timates	<u>l</u>						
General Condition: Good	Average	☐ Fair X☐ Po	oor	☐ Fire Damage				
<u>L</u>	ist Sugges	sted Repairs			<u>Ag</u>	ent Estimates		
Exterior Paint:				_	\$			
Interior Paint: <u>NEEDS PAINT</u>					\$	500.00		
Carpet: <u>NEEDS REPLACE</u>	D				\$	2500.00		
Other Flooring: SUB FLOO	R				\$	1000.00		
Kitchen: TOTAL REN	10DEL				\$	10000.00		
Bathroom(s): (1.5) TOTA	L REMODEI	_			\$	5000.00		
Plumbing: <u>TOTAL REF</u>	AIR AND R	EPLACE			\$	3000.00		
Electrical:					\$			
Roofing:					\$			
Cleaning: TRASH OU	T AND DUM	P FEES			\$100	00.00		
Landscaping:					\$			
Other:					\$			
				Total Estimate	\$	20300.00		
Reports and Inspection	ns:							
Based on Broker's Initial In	spection	of Accessible Area	as, Additional Repo	orts Are Recommei	nded	:		
	mite	Roof	☐ Well	Septic	☐ Electrical			
☐ Plumbing ☐ Hea	ating/AC	☐Mechanical	☐ Structural	☐ Geological	[☐ Other		
Pricing:								
		Pricing	Prob	able Buyer	_			
90-120 Day As-Is Price:								
90-120 Day Repair Price:	\$3500	0.00	INVESTOR					
Recommended List Price:	\$1850	0.00	INVESTOR	INVESTOR				
30day "Quick" sale as-is	\$1250	0.00	INVESTOR	INVESTOR				
Monthly rent amount:	\$400.0	00						
	•		•					

DO YOU RECOMMEND SELLING AS/IS OR REPAIRED? ____AS-IS

Please detail subject property's characteristics with respect to the following:

Location:
Condition of the Roof: Repair Replace OK X
Condition of the Interior: Water Damage? Yes No
WHERE THE WASHER WAS SITTING
Condition of the Exterior:
SEVERAL PIECES OF SIDING MISSING
Market Conditions:
SLOW
Unemployment Rate:
12.6 SECOND HIGHEST IN KENTUCKY
Comments:
Positive features:
NICE SIZE YARD, COULD BE A REALLY CUTE HOUSE, CLOSE TO ELEMENTARY SCHOOL, ROOF IS IN GOOD CONDITION

Comp Sheet:

Subject Address	Sq. Ft.	Bed	Bath	Age	Condition	Garage # of Car	Pool	Lot Size	Extras
921 N LEE	996	3	2	60	POOR	0	NO	68X150	

Comparable Listings:

Comparable Listing Address	Sq. Ft.	Bed	Bath	Age	Condition	Garage # of Car	Pool	List Date	Orig. List Price	Current List Price	Distance to subject
315 DIVISION UNIONTOWN	1044	3	1	60	POOR	0	NO	2/21/14	17500	17500	15MILE
301 SAMPSON UNIONTOWN	1025	2	1	60	POOR	2	NO	2/5/14	29000	29000	15MILE
301 N PADGETTMORGANFIELD	1100	3	1	60	FAIR	0	NO	9/16/13	35000	35000	11MILE

Comparable Sales:

Comparable Sales Address	Sq. Ft.	Bed	Bath	Age	Condition	Garage # of Car	Pool	List Date	Orig. List Price	Sold Price	Distance to subject
18 N JACKSON STURGIS	1349	3	2	50	POOR	2	NO	9/27/13	19900	17799	2MILE
909 N PIKE STURGIS	1372	3	1	60	GOOD	2	NO	9/30/13	41600	35000	2MILE
107 TURNER UNIONTOWN	1420	3	2	10	POOR	0	NO	10/15/1 3	9900	9000	15MILE

Comparable listing Comments:

LISTING 1 AND 2 I WOULD CONSIDER INHABITABLE WITHOUT MAJOR REPAIRS.

Comparable Sales Comments:

SOLD COMP 1 IS FORECLOSURE AND HAD MOLD PROBLEMS. COMP 3 HAD MAJOR WATER DAMAGE.



Checklist of Damages

Is there any vandalism?: Yes \(\subseteq \text{No } \text{\subseteq} \) If yes, Where?
Is there any graffiti?: Yes ☐ No X☐ If yes, Where?
Is there any damage that appears to be caused by an act of nature?: Yes X □ No □ If yes, Where?
SIDING ON THE NORTH SIDE OF HOUSE
Are there any broken windows?: Yes No X If yes, Where?
ALL THE WINDOWS ARE REPLACEMENT WINDOWS. THEY ARE JUST FINISHED OUT.
Are there any walls with holes larger than a quarter?: YesX \(\sum \) No \(\sum \) If yes, Where?
MUTILPLE PLACES
Are there any broken doors?: Yes \(\subseteq \text{NoX} \subseteq \text{If yes, Where?} \)
Are there any tears or holes in carpet or vinyl, or missing flooring? : Yes X No If yes, Where?
MUTILPLE PLACESSEE PICTURES
Are there any signs of water damage or mold present?: Yes \[\sum No \[\sum \] If yes, Where?
FLOORS WHERE WASHER AND REFRIGERATER WAS
Does anything appear to be missing? (i.e., built in appliances, cabinets, interior doors, water heater) : Yes X \(\sum \) No \(\sum \) If yes, Where?
NO APPLIANCES NO CABINETS DOORS NO THERMOSTAT FOR THE ONE BASE BOARD HEATER
Are there any signs of water damage or mold present?: Yes \[\sum No \[\sum \] If yes, Where?




02/27/2014





bedroom

Unfinished window





Frozen toilet kitchen



Back door

electric panel



Trash and unfinished window



Hole in floor

master bath



Master bath

bad plastering



Broken thermostat



back yard trash



Back yard

trash in building



Back yard

kitchen cabinets



Back

trash in back yard







sold 3 sold 1 sold 2



active 3 active 2 active 1